



# RMB501 Dual CV Shaft Breakdown

## Before February 2003

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1.	573020355	1	Yoke with Bridge
3.	338009000	16	Circlip
5.	208026854	1	Outer Tube Yoke
7.	348017000	6	Grease Nipple
11.	341048000	2	Flexible Pin
12.	245640360	1	Cardan Tube
13.	225500357	1	Cardan Tube
21.	208026856	1	Outer Tube Yoke
22.	412020102	4	Cross Journal Assembly
25.	208020061	2	Intermediate Yoke
27.	246000112	2	Sleeve
30.	208028551	1	Yoke with Bridge
31.	255002451	1	Ring Nut
32.	517200010	2	Cone with Collar
33.	236040328	1	Safety Tube
34.	236030328	1	Safety Tube
40.	254020410	2	Complete Shell
41.	255000011	8	Key
42.	255005110	2	Plastic Hook
51.	403000001R10	1	Complete Push Button
52.	240002461	1	Sleeve
91.	D21E04910X01	1	Half Shaft
92.	D21E04910X01	1	Half Shaft
93.	D21A0491SX01	1	Half Shaft
94.	D21A049ESX01	1	Half Shaft
95.	4E2A04901	1	Half Safety Shield
96.	412A04901	1	Half Safety Shield
97.	4D2A04901	1	Safety Shield